


# ASSEMBLY INSTRUCTION

## Langham Motion RAF PC

### Components





A  
x1



Hardware List			
a		Transformer	1
b		Charger	1

### Assembly Instructions

- ① Pull the power input wire from the back of the body, connect with the transformer and charger.



- ② Take out the wire connector from the side and connect with other pieces.




Made in China

1 of 2


# ASSEMBLY INSTRUCTION

## Langham Motion RAF PC

- ③ Find switch panel on the side of the seat cushion .



- ④ Each charger can support running maximum 3 pieces at the same time.



Made in China

2 of 2