

Isolating Connectors

700PARTD1_

1.6

VISUAL COMFORT & Co.

MODERN COLLECTION

GENERAL PRODUCT INFORMATION:




This product is suitable for indoor dry locations only.

This product is intended to be used with Tech Lighting Kable Lite system only.




1A

0.05 ALLEN
WRENCH#4-40
SET SCREW

- 1 Loosen (Do Not Remove) the six #4-40 set screws with the provided 0.05 Allen wrench to clear the side holes.

1B

0.05 ALLEN
WRENCH#4-40
SET SCREW

- 2 Feed end of one Kable Lite cable half way into the side hole of the isolating connector and tighten the three #4-40 set screws with the 0.05 Allen wrench.
- 3 Feed the other Kable Lite cable half way into the other end of the isolating connector and tighten the three #4-40 set screws with the 0.05 Allen wrench.
- 4 Repeat steps 1 through 3 for the other isolating connector.

SAVE THESE INSTRUCTIONS!

VISUAL COMFORT & CO.

7400 Linder Ave, Skokie, IL 160077

800.969.3347

www.visualcomfort.com

©2023 Visual Comfort & Co.. All rights reserved. The Visual Comfort & Co. logo is a registered trademark of Visual Comfort & Co. Visual Comfort & Co. reserves the right to change specifications for product improvements without notification