











ASSEMBLY INSTRUCTION FOR
SHADOW BOX CABINET

A		Tipping Hardware	1 SET
B		Screwdrivers (Not included)	1 PC







Tipping Hardware

