


ASSEMBLY INSTRUCTION

Langham Motion Armless PC



Components





A
x1

Assembly Instructions

- ① Pull the power input wire from the back of the body, connect with the transformer and charger.



- ② Take out the wire connector from the side and connect with other pieces.




Hardware List			
a		Transformer	1
b		Charger	1

ASSEMBLY INSTRUCTION

Langham Motion Armless PC

- ③ Find switch panel on the side of the seat cushion .



- ④ Each charger can support running maximum 3 pieces at the same time.

