


ASSEMBLY INSTRUCTION

Langham Motion RAF PC

Components





A
x1


Hardware List			
a		Transformer	1
b		Charger	1

Assembly Instructions

- ① Pull the power input wire from the back of the body, connect with the transformer and charger.



- ② Take out the wire connector from the side and connect with other pieces.






Female plug

Male plug

ASSEMBLY INSTRUCTION

Langham Motion RAF PC

- ③ Find switch panel on the side of the seat cushion .



Backward control button

Forward control button

- ④ Each charger can support running maximum 3 pieces at the same time.

