


ASSEMBLY INSTRUCTION

Langham Motion Armless PC



Components



A
x1


Assembly Instructions

- ① Pull the power input wire from the back of the body, connect with the transformer and charger.




Connect a and b

- ② Take out the wire connector from the side and connect with other pieces.



Made in China




1 of 2


ASSEMBLY INSTRUCTION

Langham Motion Armless PC

- ③ Find switch panel on the side of the seat cushion .



- ④ Each charger can support running maximum 3 pieces at the same time.



Made in China

2 of 2