



ASSEMBLY INSTRUCTION

Crawford Power Recliner RAF PC

Step 1




Step 2




| Hardware List | | | | |
|---------------|--|--------------|------------|---|
| 1 | | Body | | 1 |
| 2 | | Seat cushion | | 1 |
| 3 | | Back cushion | | 1 |
| 4 | | Charger | 3M | 1 |
| 5 | | Transformer | 29Vdc/1.8A | 1 |

Step 3



Step 4



Step 5

