



ASSEMBLY INSTRUCTION

Crawford Power Recliner Armless PC

Step 1




Step 2




Hardware List				
1		Body		1
2		Wedge back		1
3		Seat cushion		1
4		Back cushion		1
5		Charger	3M	1
6		Transformer	29Vdc/1.8A	1

Step 3



Step 4

Seat closed Seat open



Step 5

