


SHADO SCONCE

INSTALLATION DIAGRAM




WARNING:

Turn off power at circuit before wiring.
Always consult a licensed electrician.



PROVIDED HARDWARE

X1



X2

