




Gala Chandelier Canopy

15743 rA



CAUTION:

Before starting, turn off power at main circuit panel.

ADVERTENCIA:



Antes de comenzar la instalación, apague la corriente en el tablero principal.

ATTENTION:

Coupez l'alimentation avant de procéder à l'installation.



Calling for backup? Scan above to contact our team.




www.RBW.com

+1 212 388 0399


support@RBW.com

© RBW Studio LLC, 2013, 2020



What's Included: Part Configurations May Vary


Item	Qty	Part number	Description
1	1	10489-PC30	Gala Canopy Assembly Black
2	1	15713	Gala Canopy Mounting Kit
3	1	15731	Gala Driver Mounting Screw Kit
4	1	Driver	LED Driver



Installation - Driver and Powered Cables

1. Fasten driver to Crossbar via included 4-40 x 0.25in pan head screws.
2. Adjust fixture to final hang height. Trim excess Cables, slide Yellow Insulators over Cables.
3. Cap Yellow Insulators with Black Rubber Caps.

See chandelier installation instructions for mounting crossbar to substrate.



Page Intentionally Left Blank

Installation - Wiring and Canopy Screws

1. Connect Red (+) and Black (-) leads from driver to red and black leads connected to cable grippers.
2. Connect AC (L) and AC (N) leads from driver to leads in j-box.
3. Connect ground wire from canopy to ground in j-box
4. Slide Canopy upward and cover Crossbar. Secure in place with (2) 8-32 hex screws on either side of Canopy with provided allen key.
5. Congratulations! End of guide.