


SHAI SCONCE

INSTALLATION DIAGRAM



WARNING:

Turn off power at circuit before wiring.
Always consult a licensed electrician.



PROVIDED HARDWARE

X2



6-32 SET CREWS

X2

